

## Your Home Inspection Report and Pictures

**Inspector: David Rutkowski- Premier Inspections** 

tion INFO

ONLY FOR USE BY Your Name . North Olmsted, OH

File # 1234 PAGE 1



### **General Information**

Inspection date February 10, 2014

Start time 9:00 AM

Stop time 1:00 PM

Weather Cloudy, Deep Snow,

**Snow Cover** 

**Temperature** Between 0 and 10

House Type Colonial, 2 Story

**Age** 1960's

Fee (s) \$ 275

Total Fee \$ 275

Items inspected House, Garage

**NOT inspected** A/C unit(s)

**Buyer's agent** 

Listing agent

\*

\*

\*

### **Customer Information**

File # 1234

Inspection address 1234 Your Street

City/State/Zip North Olmsted, OH 44070

Client name Your Name

**Street address** 

City/State/Zip

**Home Phone** 

Cell phone

Work phone

Email 1 Your email

Address@yahoo.com

Email 2

**Email 3** 

Email 4

Attendees Buyer(s), Buyers Agent

\*

\*

# Note: This report is only part of the inspection summary, the inspectors verbal notes are needed. NOT for third party use! ${\color{blue} \mathbf{NOT}} \ \mathbf{REGISTERED}$

Premier Inspections w.premierinsp.com	items the inspector classified	_	SAFETY SUMMARY ONLY FOR USE BY Your Name , North Olmsted, OH	File # 1234 PAGE 2
Baths 1 &/or 2	Ventilation		o discharge outside. Vent discorrect to discharge positively aisy; replace.	•
Baths 1 &/or 2	Ventilation		o discharge outside. Vent disc correct to discharge positively to disy; replace.	•
Elect.	Inside Receptacles	outside, garage, kito	eptacles recommended near with the protection; and basements, some of GFCI protection; add.	•
Elect.	Outside Receptacles	GFCI protected rece garage.	eptacles recommended outsid	e and in

## Note: This report is only part of the inspection summary, the inspectors verbal notes are needed. NOT for third party use! ${\bf NOT~REGISTERED}$

Premier Inspections w.premierinsp.com	items the inspector classified as unsatisfactory items	UNSAT SUMMARY ONLY FOR USE BY Your Name , North Olmsted, OH	File # 1234 PAGE 3
w.premierinsp.com			

Exterior Rain Gutters Gutter bent/sagged; correct so water flows to down spout. Exterior Garage door Garage door opening bracket not secured. It is damaging the top of garage door. Exterior Faucet outside Spigot outside is not a freeze safe type; shut off and drain water for winter. Recommend adding a freeze safe spigot. Dripping outdoor faucet; correct for water conservation. Inter Attic insulation Recommend increasing the amount of attic insulation to at least R-38. Add insulation where missing or where gaps are. Inter Exterior doors Weatherstrip on exterior doors needs fixed/replaced. Heat Outside unit Level outside A/C unit. Elect. Secure weatherhead to house. Power entry

Premier Inspections w.premierinsp.com	MARGNL UNSAT SAFETY	- Unsatis	nal, maintenance needed  factory - repair / replace  n be a hazard  - Not applicable  - Inaccessible; partially or fully  - Typical condition	Exterior ONLY FOR USE BY Your Name , North Olmsted, OH	File # 1234 PAGE 4
A: Roof covering		INAC	newer; but as so little of the re	0% visible. The shingles visible appear oof was visible, we cannot assure that of roofer check when snow is gone.	
B: Roof sheathing		INAC	B:	100101 CHOCK WHOM SHOW IS BONC.	
C: Chimney #1		1		rain cap and spark arrestor installed to	prevent
D: Chimney #2		INAC	D:		
E: Rain Gutters	UNSAT		E: Gutter bent/sagged; correct so	water flows to down spout.	
F: Windows	MARGNL		F: Recommend window well cov		
basement					
G: Deck		OK	G:		
H: Front porch		OK	H:		
I: Porch		N/A	I:		
J: Steps		OK	J:		
K: Siding		OK	K:		
L: Trim		OK	L:		
M: Yard grade		INAC	M: Yard Grade unable to determine	ne due to deep snow cover.	
N: Trees/shrubs		OK	N:		
O: Garage		OK	O:		
P: Garage door	UNSAT		P: Garage door opening bracket i	not secured. It is damaging the top of ga	rage door.
Q: Drive/walk		INAC	Q: Unable to determine due to de		
R: Faucet outside	UNSAT			afe type; shut off and drain water for wi	
			conservation.	afe spigot. Dripping outdoor faucet; con	rect for water
S: Other		N/A	S:		



Gutters are sagging. Need to be leveled to prevent water from running over onto foundation.



Rain cap/Spark arrestor is needed on **BOTH** chimneys.

Roof viewed from Ground Type of roof Roof covering Siding type Gable Asphalt Vinyl Garage Type Roof Layers

2 Car, Attached 2 Layer

Note: This report is only part of the inspection summary, the inspectors verbal notes are needed. NOT for third party use!  ${\color{blue} NOT~REGISTERED}$ 

	MARGNL		nal, maintenance needed		Structure		File # 1234
Premier	UNSAT	- Unsati	sfactory - repair / replace	2	ONLY FOR USE	BY Your Name	PAGE 5
Inspections	SAFETY		an be a hazard		, North Olmsted,		
Top-volunito		N/A	- Not applicable				
w.premierinsp.com		INAC	- Inaccessible; partially	or fully			
. apremierinspresin		OK	- Typical condition				
	]	İ					
A: Foundation		OK	A:				
B: Found. cracks		OK	B:				
C: Sills		OK	C:				
D: Joists		OK	D:				
E: Main beam		OK	E:				
F: Columns		OK	F:				
G: Wood rot		N/A	G:				
H: Insect damage		OK	H: No signs of active	wood destro	ying insect activi	ty (termite or carpenter	ants) seen in
			accessible areas.				·
I: Bsmt. water		OK				e inspection; water may	enter
			periodically.				
J: Sump pump		OK	J:				
K: Air moist. Bsmt.		OK	K:				
L: Bsmt. entry		OK	L:				
M: Rafter/truss		OK	M:				
N: Other		N/A	N:				
T. Guiei		1 1/12					
	I.						
SYSTEM NOTES							
Support structure	Basement	Crawle	nace	Main beam	Steel		
Foundation	Block	i, Ciawi S	puoe	Column	Steel		
Wall type	Wood fran			Roof struct			
Floor type	Wood fran						

Premier	MARGNL UNSAT	- Unsati	nal, maintenance needed sfactory - repair / replace	Kitchen ONLY FOR USE BY Your Name	File # 1234 PAGE 6
Inspections w.premierinsp.com	SAFETY	- Is or ca N/A INAC OK	an be a hazard  - Not applicable  - Inaccessible; partially or fully  - Typical condition	, North Olmsted, OH	
A: Dishwasher		ок	A:	-	
B: Stovetop		OK	B:		
C: Oven		OK	C:		
D: Refrigerator		OK	D:		
E: Garbage disposal		OK	E:		
F: Microwave		OK	F:		
G: Kit. vent		OK	G:		
H: Trash compactor		N/A	H:		
I: Countertop	MARGNL		I: Caulk countertop to backspl	ash/wall.	
J: Kitchen cabinets		OK	J:		
K: Sink kitchen		OK	K:		
L: Water pipes		OK	L:		
M: Drainage		OK	M:		
N: Drain pipe		OK	N:		
O: Other		N/A	O:		



Caulk around kitchen backsplash. Open gap needs to be sealed.



Kitchen garage entry door needs to be an auto- closure for safety/fire hazard.

**Appliances** Stovetop, Microwave, Dishwasher, Oven,

Premier Inspections w.premierinsp.com	MARGNL UNSAT SAFETY	- Unsati	nal, maintenance needed sfactory - repair / replace an be a hazard - Not applicable - Inaccessible; partially or fully - Typical condition	Baths 1 &/or 2 ONLY FOR USE BY Your Name , North Olmsted, OH	File # 1234 PAGE 7
A: Bath #1 Location B: Tub/shower C: Sink D: Toilet	CARPINA	OK OK OK OK	master. B: C: D:	bath located on the second floor. Iden	
E: Ventilation	SAFETY			e outside. Vent discharges into the atti outside. Vent fan noisy; replace.	c/soffit; correct
F: Water flow G: Drainage H: Floor I: Bath #2 Location		OK OK OK OK	F: G: H: I:This was the full	l bath located on the second floor. Idea	ntified as the
J: Tub/shower K: Sink L: Toilet		OK OK OK	main. J: K: L:		
M: Ventilation	SAFETY			e outside. Vent discharges into the atti	c/soffit; correct
N: Water flow O: Drainage P: Floor		OK OK OK	N: O: P:	outside. Vent fan noisy; replace.	



Both upstairs bathroom vents exhaust into attic. Need to exhaust outside for health safety.



Both upstairs bath vents are noisy.

#1 Floor covering Plastic sheet Tub/shower wall Plastic or fiberglass Power fan Vent method

#2 Floor covering Tub/shower wall Vent method

Laminant Plastic or fiberglass Power fan

Note: This report is only part of the inspection summary, the inspectors verbal notes are needed. NOT for third party use!  $NOT\ REGISTERED$ 

	MARGNL	- Margi	nal, maintenance needed		Baths 3 &/or 4	File # 1234
Premier	UNSAT		sfactory - repair / replace	2	ONLY FOR USE BY Your Name	PAGE 8
Inspections	SAFETY		an be a hazard		, North Olmsted, OH	111020
Theory		N/A	- Not applicable		, 1101 til Omisicu, OH	
		INAC	- Inaccessible; partially	or fully		
w.premierinsp.com		ОК	- Typical condition	·		
A: Bath #3 Location	Ī	ок	A·Thic	was the 1/2 1	oath located on the first floor.	
B: Tub/shower		N/A	B:	was the 1/2	outh focuted on the first floor.	
C: Sink		OK	C:			
D: Toilet		OK	D:			
E: Ventilation		OK	E:			
F: Water flow		OK	F:			
G: Drainage		OK	G:			
H: Floor		OK	H:			
I: Bath #4 Location		N/A	I:			
J: Tub/shower		N/A	J:			
K: Sink		N/A	K:			
L: Toilet		N/A	L:			
M: Ventilation		N/A	M:			
N: Water flow		N/A	N:			
O: Drainage		N/A	O:			
P: Floor		N/A	P:			
	•					
ONTO THE REST OF THE CASE OF T						
SYSTEM NOTES	DI- "			"A <b>-</b> "	du	
#3 Floor covering Tub/shower wall	Plastic sh N/A	eet		#4 Floor co Tub/showe	vering r wall	
Vent method	Power far	า		Vent metho		
v one mound	. Ower rai			v one moule	<del>-</del>	

Premier Inspections w.premierinsp.com	MARGNL UNSAT SAFETY	- Unsati	nal, maintenance needed sfactory - repair / replace an be a hazard - Not applicable - Inaccessible; partially or fully - Typical condition	Inter ONLY FOR USE BY Your Name , North Olmsted, OH	File # 1234 PAGE 9
A: Attic venting		ОК	A:		

	]			
A: Attic venting		ОК	A:	
B: Attic insulation	UNSAT		B:	Recommend increasing the amount of attic insulation to at least R-38. Add
				insulation where missing or where gaps are.
C: Openings attic		OK	C:	
D: Water leaks		OK	D:	
E: Basement		OK	E:	
insulation				
F: Fireplace/stove #1		N/A	F:	
G: Fireplace/stove #2		OK	G:	
H: Flue		OK	H:	Have flues cleaned and evaluated by chimney company to verify flue is operational
				and functional. Recommend cleaning of wood burning units yearly.
I: Clearances		ОК	I:	
J: Firebox		OK	J:	
K: Ceilings		OK	K:	
L: Walls		OK	L:	
M: Floors		OK	M:	
N: Door fit		OK	N:	
O: Stairs		OK	O:	
P: Smoke alarm	MARGNL		P:	Smoke alarms were not evaluated as part of the home inspection. It is
				recommended to replace Smoke and CO alarms in house to insure alarms are
				working and have the latest technology. Some additional carbon monoxide alarms
				are recommended.
Q: Exterior doors	UNSAT		Q:	Weatherstrip on exterior doors needs fixed/replaced.
R: Windows		OK	R:	
S: Storm windows		N/A	S:	
T: Skylights		N/A	T:	
U: Other		N/A	U:	
	1	I	1	



Front door weather stripping is open.



Garage entry door weather stripping is missing.

Forced venting	None	(
Vent types	Gable, Soffit, Roof	,
Attic Insulation- Type/	Fiberglass 3.5"/R-11	,
Bsmt Insulation- Type/	None	

Crawl Insulation-Vapor retarder-Attic: not visible, Basement: N/A, Crawl Attic entered Yes

Basement entered Yes Note: This report is only part of the inspection summary, the inspectors verbal notes are needed. NOT for third party use!  ${\color{blue} NOT~REGISTERED}$ 

Premier	MARGNL UNSAT	- Unsatis	nal, maintenance needed sfactory - repair / replace		Plumb ONLY FOR	R USE BY Your Name	File # 1234 PAGE 10
Inspections	SAFETY		n be a hazard		, North Oln		
w.premierinsp.com		N/A INAC OK	<ul><li>Not applicable</li><li>Inaccessible; partially</li><li>Typical condition</li></ul>	or fully			
A: Water heater	MARGNL			d and could fa	ail at any tii	me. Plan on replacing withi	n 5 years.
B: Water pipes C: Water supply D: Water pump E: Drainage F: Drain pipe G: Cross connection H: Other	MARGNL	OK OK N/A OK OK N/A	B: C: D: E: F: G: H:	d and could is	an at any th	me. Plan on replacing within	n 5 years.
SYSTEM NOTES  Water heater type Water service pipe Water supply pipes Water supply type	Gas, 40 G Copper Copper City water			Waste pipe Main shut-c	offs for	Plastic Water-basement, Fuel-at m	eter

Premier Inspections w.premierinsp.com	MARGNL UNSAT SAFETY	- Unsatis	al, maintenance needed factory - repair / replace n be a hazard - Not applicable - Inaccessible; partially or fully - Typical condition	Heat ONLY FOR USE BY Your Name , North Olmsted, OH	File # 1234 PAGE 11
A: Heat system	MARGNL			operating at the time of the inspection, we gest replacing to avoid a breakdown, or at	
B: Gas leakage C: Circulator D: Heat exchanger E: Relief valve		N/A N/A INAC	B: C: D: Areas of the heat exchanger inspector could not discover E:	were not visible; these areas may have fai	lures the
F: Asbestos G: AC/HP H: Outside unit	UNSAT	N/A INAC	F: G: Temperature was too cold to H: Level outside A/C unit.	evaluate the A/C system.	
I: Coils/fans J: Air ducts K: Refrigerant lines	MARGNL	INAC OK	<ul><li>I:</li><li>J:</li><li>K: Insulation on refrigerant line</li></ul>	s is damaged/missing; replace.	
L: Room heat M: Water heater	MARGNL	N/A	L:	ear the end of its predicted life; budget to	replace at any
N: Other		N/A	N:		




AC unit needs leveled for proper operation.

Type of system Complete system Type of fuel Air cond. Forced Air Furnace with AC Gas Central

	NSAT AFETY	- Unsatist - Is or car N/A INAC	al, maintenance needed factory - repair / replace n be a hazard - Not applicable - Inaccessible; partially or fully - Typical condition	Elect. ONLY FOR USE BY Your Name , North Olmsted, OH	File # 1234 PAGE 12
4 D	TINICAE				

	OK	- Typical Colluition
A: Power entry UNSAT		A: Secure weatherhead to house.
B: Main panel	OK	B:
C: Main ground	OK	C:
D: Over current	OK	D:
E: Moisture	OK	E:
F: Junction box	OK	F:
G: Wire routing	OK	G:
H: Wire outside	OK	H:
I: Plumbing bonding.	OK	I:
J: Duct bonding	OK	J:
K: Inside <b>SAFETY</b>		K: GFCI protected receptacles recommended near water, outside, garage, kitchen and
Receptacles		basements, some of these areas do not have GFCI protection; add.
L: Outside SAFETY		L: GFCI protected receptacles recommended outside and in garage.
Receptacles		
M: Extra tests	N/A	M:
N: Sub panel	OK	N:
O: Other	N/A	0:



GFCI outlet needed in garage.



Main electrical mast needs secured to house.

Service type Main disconnect Overhead 100 AMP Wire type(s) Main panel BX (armored), Romex Basement Subpanel present Main Breaker/fuse

Yes, Evaluated Yes Basement

### NOT REGISTERED



### **APPENDIX 1**

ONLY FOR USE BY Your Name , North Olmsted, OH File # 1234 PAGE 13




Exterior: Spigot is leaking and freezing. Replace with freeze proof spigot.



Exterior: Vent on exterior is ???? Needs to be sealed to prevent critters from entering house.



**Exterior: Recommend window well covers for basement windows.** 



Exterior: Garage door opening bracket not secured. It is damaging the top of garage door.



Elect.: Make sure to use appropriate dimmable bulbs for any dimmable switch light.



Inter: Bad attic insulation, compressed, damaged or missing.

Note: This report is only part of the inspection summary, the inspectors verbal notes are needed. NOT for third party use!  $NOT\ REGISTERED$ 



# **APPENDIX 2**

File # 1234 PAGE 14

**ONLY FOR USE BY Your Name** , North Olmsted, OH



Elect.: Need GFCi outlet on exterior.